
ASSEMBLY INSTRUCTIONS FOR ODOM CONSOLE (ODM-400)



- 1 Unpack all parts and hardware carefully.
 - Place table top(A)upside down on soft surface. (soft pad,clean moving blanket as an example)
- arefully. 2 Thread bolts with washers into holes.
 Tighten using allen wrench E

- **3** Check all connections make sure everything is tight.
 - Carefully lift and rotate to upright position.

